



# सर्वेक्षणप्रयोगशाला

## Survey Lab

### Major Equipments:

- Total Station
- Theodolite
- Auto-Level
- Dumpy Level
- Plain Table
- Prismatic compass
- Surveyor compass



### Newly Procured Equipments

- Total Station (Trimble C5)



### **In Charge**

**Prof. A.K. Dwivedi**  
(9425737429)

### **Physical In Charge:**

**Mr. Rajendra Pawse**  
(9753588069)

**Department Of Civil Engineering**



# सर्वेक्षणप्रयोगशाला

## Survey Lab

### **SAFETY PRACTICES TO BE FOLLOWED IN LABORATORY:**

- Always wear shoes before entering lab.
- Do not touch anything without permission of instructor /lab assistant.
- Check electrical connections before starting the equipment .
- Do not unplug any electrical connection.
- Do not put your hand while the machine is in operation.
- Do not tamper measuring instrument.
- Do not open the casing of the equipment
- Switch off the power supply to the experimental.
- Any injuries should be reported immediately for proper care.



### **DO's**

- Be on time, at the start of the lab period, there will be a short introduction to the experiment you will perform that day.
- Thoroughly CLEAN your laboratory work space at the end of the laboratory session.
- Maintain silence and clean environment in the lab and put bags at allocated Locations.

### **DON't**

- Do not try to run and operate any machine without permission and knowledge of the lab Personnel
- In case of any mishap - Do not be Panicky, be calm but quick report at once to the Lab Personnel.
- Do not eat or Drink in the Lab room at any time.